## **Topic 6: Check/Prepare the Inspection**

#### Introduction:

This topic will demonstrate how to check/prepare the inspection for completion using the PASS DCD 2.1 software.


## Walkthroughs:

- Walkthrough 11 Check/Prepare the Inspection
- Walkthrough 12 View the Inspection Report

#### Walkthrough 11: Check/Prepare the Inspection


#### **Step 1:** Single-click the **Check/Prepare/Import** tab.

The *Check/Prepare/Import* screen for unfinished/incomplete inspections opens.



- Step 2: If an inspection is incomplete, the system indicates those areas which need to be completed. Complete the inspection as indicated before completing the next step.
- **Step 3:** Single-click the **Check/Prepare** tab.

The *Check/Prepare/Import* screen for complete inspections opens.



Note: If there are any life-threatening hazards reported during the inspection, single-click the Life Threatening Hazards Report button to the view the report. The report will include information about the Life Threatening Health and Safety Hazards observed during the inspection. The Life Threatening Hazards Report button will not appear on the Check/Prepare/Importscreen if none were reported during the inspection.

### Walkthrough 12: View the Inspection Report


**Step 1:** Open Windows Explorer.

Step 2: Locate filename reac\_dcd.mdb using the following path:

C:\ Program Files \ Hudinsp\ data \ reac\_dcd.mdb


Step 3: Double-click reac\_dcd.mdb file to open.

The Microsoft Access page opens.




Step 4: Single-click the Reports tab.

The Reports page opens.



Step 5: Double-click the **repDeficiency** icon.
The *Enter Parameter Value* message box opens.



- Step 6: Enter the inspection number in the **Inspection** field.
- Step 7: Single-click the **OK** button. The *Deficiency Report* opens.

# **Deficiency Report**

Inspection No: 115

Property: 200 Lakeshore Drive Brighton

MA 02135

Inspection Date: 8/9/99 Phone: 6177824567

Fax: 6177821456

Scattered Site? N E-mail Address: crockwell@meadows.co

m

Inspected Item	NOD/OD	Observation	Severity	Location	/Comments
BldgExt					
Building 1 Lighting					
Security of the security of th	OD	Missing/Broken Bulbs	Major	Loc ation:	Comment
No.	OD	Broken Fixtures	Major	Location:	Comment
	OD	Missing/Broken Bulbs	Major	Location:	Comment
7	OD	Broken Fixtures	Major	Location:	Comment
	OD	Missing/Broken Bulbs	Major	Loc ation:	Comment
	OD	Broken Fixtures	Major	Location:	Comment
CA					
Building 1					
Trash Collection Areas		92000		200	
	OD	Chutes - Damage d/Missing Components	Major	Location:	Comment:
	OD	Damage d/Missing	Major   Major	Loc ation:	Comment:
	k	Damage d/Missing Components Chutes - Damage d/Missing			
	OD	Damage d/Missing Components Chutes - Damage d/Missing Components Chutes - Damage d/Missing	Major	Location:	Comment
Areas	OD	Damage d/Missing Components Chutes - Damage d/Missing Components Chutes - Damage d/Missing	Major	Location:	Comment
Areas  DU  Building 1 - Un	OD	Damage d/Missing Components Chutes - Damage d/Missing Components Chutes - Damage d/Missing	Major	Location:	Comment
Areas  DU  Building 1 - Un	OD	Damage d/Missing Components Chutes - Damage d/Missing Components Chutes - Damage d/Missing Components Chutes - Damage d/Missing Components	Major	Location:   Location:	Comment Comment

Friday, August 13, 1999

Page 1 of 3